# TOTAL ECLIPSE® **ULTRA HIGH-SPEED FLOOR COATING**

Specially formulated for high speed buffing to produce maximum shine in minimum time. Heat activated polymer compounds enhance the wet-look shine with frequent burnishing.

#### **FEATURES**

- Ideal for frequent maintenance program (5-7 days/week)
- Extremely durable
- Brilliant wet-look gloss
- Self-sealing
- Classified by UL as to slip resistance only



## RECOMMENDED FLOOR SURFACES

All resilient tile flooring

#### PRODUCT DATA

Description: Acrylic co-polymer emulsion

Appearance: Milky white Slight ammoniacal Fragrance: 2500-3000 sq ft per gal Coverage: 61-74 sq m per liter

Non-Volatile Solids: 20.0 ± 0.5%, ASTM 2834-95 (2001)

>85, ASTM D1455-87 (1997) Specular Gloss (60°):

**Buffability:** Excellent

Detergent Resistance: Excellent D3207-92 (1996) e1

Removability: Excellent

Viscosity (Brookfield): <10 centipoise @ 68°F (20°C)

Slip Resistance: Meets ASTM D2047-99 requirements

Classified by UL as to slip resistance only.

Drying Time: 20-30 minutes

Shelf Life: 1 year, ASTM D1791-93 (1998)

Density: 8.6 lb per gal @ 68°F

1.03 kg per liter @ 20°C

Freeze/Thaw: Passes 3 cycles ASTM D3209-93 (1998)

## **PRECAUTIONS**

Keep out of reach of children. Keep container sealed when not in use. Avoid freezing. If frozen, allow to return to room temperature slowly and then mix thoroughly before using.

#### ORDERING INFORMATION

Product #102: 2 x 2.64 gallon per case (2 x 10 liter) Product #102MP: 4 x 1.06 gallon per case (4 x 4 liter)



## **DIRECTIONS FOR USE: INITIAL APPLICATION**

- 1. Remove old coating and sealer with the recommended Pioneer Eclipse stripper following label directions. For optimum results, use a Pioneer Eclipse autoscrubber or stripping machine with recommended Pioneer Eclipse pads or brushes.
- 2. Use a clean mop or autoscrubber to rinse the floor twice using a Pioneer Eclipse neutral cleaner. Rinse floor again with clean, cold water and allow to dry.
- 3. Apply 4-6 coats of Total Eclipse Ultra High-Speed Floor Coating with a clean, synthetic mop and allow to dry between coats. On old or porous floors and in cases of extreme traffic conditions, use recommended Pioneer Eclipse sealer prior to applying Total Eclipse Ultra High-Speed Floor Coating.

Note: Do not exceed a total initial application of 6 coats combined coating and sealer.

4. Allow floor to dry thoroughly between coats and prior to burnishing.

Note: To prevent contamination do not pour unused product

from bucket into original container.

## **DIRECTIONS FOR USE: ROUTINE MAINTENANCE**

- 1. Sweep floor daily with either a mop treated with EnviroStar Green® Dust Mop Treatment, or with an untreated dust mop.
- 2. Mop or autoscrub as necessary with a Pioneer Eclipse neutral cleaner following label directions.
- 3. Restore as needed with a Pioneer Eclipse maintainer.
- 4. Burnish as desired with recommended Pioneer Eclipse machine and pad.
- 5. As needed, perform a deep scrub and recoat applying an additional 1-2 coats of Total Eclipse Ultra High-Speed Floor Coating
- 6. Allow floor to dry thoroughly between coats and prior to burnishing.
- 7. When stripping is necessary, remove Total Eclipse Ultra High-Speed Floor Coating with a recommended Pioneer Eclipse stripper.



# TOTAL ECLIPSE ULTRA HIGH-SPEED FLOOR COATING

LAST REVISION DATE: 05/31/04 MANUFACTURER: Pioneer Eclipse® Corporation Sparta, NC 28675 Phone: 1-336-372-8080 FOR CHEMICAL EMERGENCY: Spill, Leak, Fire, Exposure or Accident CALL CHEMTREC - Day or Night 1-800-424-9300 Toll Free in the Continental US, 483-7616 in DISTRICT OF COLUMBIA. For calls originating outside the US: Call Collect 1-202-483-7616 Washington, DC.

#### SECTION IV: FIRE AND EXPLOSION DATA

FLASH POINT: Non-combustible **EXPLOSIVE LIMITS:** UPPER: N/A LOWER: N/A

**EXTINGUISHING MEDIA:** N/A SPECIAL FIRE FIGHTING PROCEDURES: None **HAZARDOUS COMBUSTIBLE PRODUCTS: None** 

UNUSUAL FIRE AND EXPLOSION HAZARDS: Materials can splatter above 100°C / 212°F.

HAZARDOUS POLYMERIZATION: Will not occur.

HAZARDOUS DECOMPOSITION PRODUCTS: N/A

INCOMPATIBILITY (MATERIALS TO AVOID):

## SECTION VIII: SPECIAL PROTECTION

## PERSONAL PROTECTIVE EQUIPMENT (PPE)

EYES: None required under normal conditions of use. Safety glasses recommended. SKIN: If prolonged or repeated contact is

possible, chemical-resistant clothing (e.g., rubber gloves) is recommended.

**RESPIRATORY:** No respiratory protection is required if ventilation is adequate.

**ENGINEERING CONTROLS:** Good general room ventilation is expected to be adequate. Local exhaust ventilation (e.g., fans) may be necessary when general ventilation does not keep girborne concentrations below any exposure limits.

## SECTION I: GENERAL INFORMATION

PRODUCT NAME: Total Eclipse Ultra High-Speed Floor Coating

**PRODUCT #: 102** 

PRODUCT TYPE: Acrylic co-polymer emulsion PRECAUTIONS: Possible skin and eye irritant. Keep container sealed when not in use. Keep out of reach of children.

HEALTH: 1 FLAMMABILITY: 0 **REACTIVITY**: 0 NFPA HAZARD RATINGS

4-EXTREME 3-HIGH 2-MODERATE 1-SLIGHT 0-INSIGNIFICANT



## SECTION II: HAZARDOUS INGREDIENTS

INGREDIENT: \*Diethylene glycol monoethyl ether CAS#: 111-90-0

%: 5-10 OSHA PEL: N/E ACGIH TLV: N/E

LD 50 SPECIES & ROUTE: 5.5 g/kg rat, oral

9.0 g/kg rabbit, skin

\* This chemical is subject to the reporting requirements of Section 313 of SARA Title III.

N/E = Not Established, N/L = Not Listed, N/A = Not Applicable

#### SECTION III: PHYSICAL/CHEMICAL DATA

APPEARANCE: Milky white PHYSICAL STATE: Liquid **pH:**  $9.0 \pm 0.5$ 

BOILING POINT: 100°C / 212°F **EVAPORATION RATE:** Less than water FREEZING POINT: 0°C / 32°F VAPOR DENSITY: Greater than air **VOLATILE BY WEIGHT:**  $80.0 \pm 0.5\%$ VAPOR PRESSURE: Less than water DENSITY: 8.6 lb per gal @ 68°F 1.03 kg per liter @ 20°C

**SOLUBILITY IN WATER: Miscible** 

# **REACTIVITY CONDITIONS: None** SECTION VI: HEALTH HAZARD DATA

SECTION V: REACTIVITY DATA

Strong acids and bases

**STABILITY: Stable** 

EYES: Slightly irritating to eyes. For eye contact, flush with a large amount of water for at least 15 minutes. See a physician if irritation persists. SKIN: Slightly irritating to skin upon repeated or prolonged contact. For skin contact, wash affected areas with soap and water. INHALATION: Vapor or mist may cause irritation of the eyes, nose, throat and lungs. For overexposure, move subject to fresh air.

INGESTION: May cause irritation to mouth, esophagus and stomach. If ingested, drink several glasses of water and do not induce vomiting. Seek medical attention.

CHRONIC EFFECTS AND MEDICAL CONDITIONS AGGRAVATED BY OVEREXPOSURE: Prolonged or repeated contact can cause drying, defatting and dermatitis to skin.

**CARCINOGEN:** Non-carcinogenic **REPRODUCTIVE EFFECTS: N/E TERATOGENICITY:** N/E MUTAGENICITY: N/E

THRESHOLD LIMIT VALUE: See Section II.

## SECTION VII: SPILL, LEAK & DISPOSAL PROCEDURES

SMALL SPILLS: Absorb spill with inert material (e.g. sand, earth) and dispose of as waste material in accordance with local, state and federal regulations.

LARGE SPILLS: Keep spectators away. Floors may be slippery; use care to avoid falling. Dike and contain spill with inert material (e.g. sand, earth). Transfer liquid to containers for recovery or disposal and solid diking material to separate containers for disposal. Keep spills and cleaning runoff out of sewers and open bodies of water. WASTE DISPOSAL: Dispose of as waste material in accordance with local, state, and federal regulations.

#### SECTION IX: SPECIAL PRECAUTIONS

## HANDLING AND STORAGE:

Storage temperature (MAX. 60°C / 140°F) (MIN. 1°C / 34°F)

OTHER PRECAUTIONS: Keep from freezing; product may coagulate.

## SECTION X: ADDITIONAL INFORMATION

Neither this data sheet nor any statement contained herein grants or extends any license. expressed or implied, in connection with patents issued or pending which may be the property of the manufacturer or others. The information in this data sheet has been assembled by the manufacturer based on its own studies and the work of others. The manufacturer makes no warranties, expressed or implied, as to the accuracy, completeness or adequacy of the information contained herein. The manufacturer shall not be liable (regardless of fault) or the vendee, the vendee's employees or anyone for any direct, special or consequential damages arising out of or in connection with the accuracy, completeness, adequacy or furnishing of such information.

This MSDS has been provided to you in accordance with the OSHA HAZARD COMMUNICATION STANDARD (29CFR1910.1200).

\*\*\*IMPORTANT SAFFTY INFORMATION DO NOT DISCARD\*\*\* \*\*PLEASE ROUTE TO COMPANY SAFETY OFFICER\*\*

